state Virginia	COUNTY TOWN OR VICINITY King William Acquinton
INDEX NUMBER	MONUMENT Winterham
REPRESENTED IN NEGATIVE FILE	HA.B.S. SURVEY NO. U.A. 761 Location: State Highway 629 Period: c. 1815
PUBLISHED PHOTOGRAPHS	Present condition: poor Custody: poor
PUBLISHED DRAWINGS	Description: Main portion brick first story, frame second story, with dormers in attic.
	Large exterior brick chimney one end. Story and a half frame addition one end with dormers. Shingle roofs.
e 2	10-444 HISTORIC AMERICAN BUILDINGS SURVEY

Prepared by Eugene R. Bradbury